

HISTORIC AMERICAN BUILDINGS SURVEY

INDEX TO PHOTOGRAPHS

HABS  
MO,  
95-SALU.V,  
2B-

Jefferson Barracks  
Jefferson Barracks Historical Park  
St. Louis vicinity  
St. Louis County  
Missouri

HABS No. MO-1809B

The Piaget-van Ravenswaay Survey photographs taken in the 1930s and 1940s had facsimile negatives made in 1985 because of the non-archival condition of the original nitrate and di-acetate base negatives. The HABS reference photoprint is a contact print from the facsimile negative.

LABORERS' HOUSE

- MO-1809B-1 Exterior view. Restoration complete.  
ca. 1957-60
- MO-1809B-2 Interior, common room, first floor. During restoration.  
1957-8.
- MO-1809B-3 Interior, common room, first floor. Restoration almost complete.  
ca. 1957-60
- MO-1809B-4 Interior, common room, first floor. After restoration.  
1959-60
- MO-1809B-5 Interior, stairway to second floor. During restoration.  
ca. 1957-60
- MO-1809B-6 Interior, corner fireplace in second floor bedroom, as uncovered  
prior to restoration.  
1957-58.
- MO-1809B-7 Interior, second floor bedroom. Restoration almost complete.  
1957-58.
- MO-1809B-8 Interior, second floor bedroom. Restoration complete.  
1960.
- MO-1809B-9 Interior, adjoining second floor bedroom, corner fireplace as  
uncovered prior to restoration.  
ca. 1957-60

JEFFERSON BARRACKS  
HABS No. M0-1809B(page 2)  
Index to Photographs

- M0-1809B-10 Interior, adjoining second floor bedroom. Restoration almost complete  
ca. 1957-60
- M0-1809B-11 Interior, second floor hall chamber or wash room. Restoration complete.  
ca. 1957-60
- M0-1809B-12 Exterior. Area behind Laborers' House showing site archaeology and site improvement.  
ca. 1957-60